MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20) $FEB = 0.9 \cdot 1982$

Section I

MANUFACTURER'S NAME

RAM CHEMICALS - Whittaker Corporation

STREETADDRESS 210 E. Alondra Blvd.

1/25/77

CITY, STATE, AND ZIPCODE Gardena, CA 90248

EMERGENCY TELEPHONE NO. (213) 321-0710

'RODUCTCLASS Plastics release agent

MANUFACTURERS CODE IDENTIFICATION

87-X26

NPCA 1-72

Sect	ion II — HAZ	ARDOUS	INGREDIE	NTS	•.	
NGREDIENT		PERCENT		LV mg/m³	LEL	VAPOR PRESSURE
Alcoholic & Aliphatic hydrosolvent mixture	ocarbon	96.5	400–500	toració autoració Noració Les Constructorios Noracións	1.2	•
				लुक्ति संपर्देऽ २०४४- ४०-४४-४४-४ २१९ ५ ४-४४-४४-४		
	Section III -	– PHYSIC	AL DATA			
DILING RANGE 180°-210°F		VAPOR DE	NSITY X	HEAVIER, O. L.	LIGHTER	, THAN AIR
/APORATION RATE FASTER X SLOWER,	THAN ETHER	PERCENT VOLATI BY VOLUME	LE 06.5	WEIGHT PER GALLON	6.4	
Section I\	/ — FIRE AN	D EXPLOS	ION HAZ	ARD DATA		
TINGUISHING MEDIA FORM OF CO2, d	ry chemica	1, CCl ₄	ers rede er teori.			LEL 1.2

	Section V — HEALTH HAZARD DA
THRESHOLD LIMIT VALUE 400-5 EFFECTS OF OVEREXPOSURE Mil	00 ppm d irritation of eyes, nose and throat above 400 ppm.
May	induce mild narcosis.
All the second of the second o	
EMERGENCY AND FIRST AID PROCEDUR	Move patient to fresh air. For eye or skin contact, flush thoroughly with water; obtain medical attention eyes.
	Section VI — REACTIVITY DATA
STABILITY UNSTABLE X UNCOMPATABILITY (Materials to avoid) HAZARDOUS DECOMPOSITION PRODUCT	STABLE CONDITIONS TO AVOID Open flame.
	MAY OCCUR WILL NOT OCCUR
CONDITIONS TO AVOID	Section VII — SPILL OR LEAK PROCEDURES
; the first	
STEPS TO BE TAKEN IN CASE MATERIAL I	HELEASED ON SPILLED ROMOVE BOXIOGS OF FINANCE
WASTEDISPOSAL METHOD Pick	up with inert absorbent and discard. Dissipate vapors.
Sec	tion VIII — SPECIAL PROTECTION INFORMATION
	sually needed, unless concentrations are excessively high.
÷	
and the state of t	a magaille ann an airean an t-airean a Tagailte an t-airean an t-
Mormal vent	ilation adequate as with other solvent materials.
	mally needed. suggested in case of splashes.
	Section IX — SPECIAL PRECAUTIONS
place, well away fro tainer after use. OTHER PRECAUTIONS Keep aw	GANDSTORING Treat as flammable solvent blend. Store in cool m all heat sources, sparks and open flames. Close con- vay from children.